



Rajasthan Medical Services Corporation Ltd.

D- Block, Swasthya Bhawan, Tilak Marg, C-Scheme JAIPUR (Raj)

Ph. No. 0141-2223887, Fax No. 0141-2228065

CIN:U24232RJ2011SGC035067

E-Mail -rmsc@nic.in, edepmrmisc-ri@nic.in

F-8(315)RMSC/EPM/M-3/2017-18/NIB-275/928

Date: 28/2/18


Office Order

List of bidders declared responsive/non responsive as per documentary evaluation & technical evaluation of F-8(315)RMSC/EPM/M-3/2017-18/NIB-275/5500 Dated: 13.11.2017, technical bid opening date 10.01.2018. The list of bidders declared responsive/non responsive as per decision taken in the purchase committee dated 28.2.2018 headed by M.D., RMSCL.

S. No.	Name of Tenderer Firm	Name of Quoted Item	Responsive/ Non responsive	Remark
1.	M/s York Scientific Industries Pvt. Ltd., 8/6E, Site IV, Sahibabad Industrial Area, Distt. Ghaziabad (U.P.)-201 010 Email:- ysipl@yorco.com	Hot Air Oven, Pasteurizer/Shaker Bath and Laminar Air Flow (Small machine Type)	Responsive	Responsive
2.	M/s Sudarshan Chemicals, Sudarshan Building, Jhalawar Road, Kota-320007 Email- sudarshanchemicals@gmail.com	Hot Air Oven	Non-Responsive	1. Thermal loss is prevented by filling mineral wool (insulation) in space between the outer body & inner chamber. उन्हे के दौरान poor insulation पाया गया। 2. Door gasket fixed on the double walled door for proper sealing. उन्हे के दौरान poor sealing पायी गई। इस प्रकार Non-Responsive है।
		Laminar Air Flow (Small machine Type)	Responsive	Responsive
3.	M/s National Enterprises, Plot no. 138, DIC Industrial Area, Baddi, Solan. H.P. 173205 Email:- info@nationalgroupinc.com	Hot Air Oven and Laminar Air Flow (Small machine Type)	Non-Responsive	Non-Responsive FMD की राशि बैंकर चैक या Demand Draft के रूप में जमा न कराकर F.D.R. जमा कराई गई है जो मान्य नहीं है। यह mandatory document है। टेण्डर फीस का Demand Draft MD, RMSCL के नाम प्रस्तुत नहीं किया जाकर MD, RISI के पक्ष में प्रस्तुत किया है जो निगम में जमा नहीं हो पाया। यह mandatory document है।
4.	M/s Electrocraft (India) Pvt., Plot No. 35, Sector-II, The Vasai Taluka Co-op Industrial Estate, Gaurajpada, Vasai (E) 401208 Palghar Maharashtra Email :- contact@eltekindia.com , sales@eltekindia.com	Hot Air Oven	Responsive	Responsive
5.	M/s P.L. Tondon & Co. 205-B, Apra Plaza Plaza Building Comercial Complex, Road no. 44, Pitampura, New Delhi 110034 info@tancolabproducts.com , tancolbproducts@gmail.com	Hot Air Oven	Non-Responsive	1. Thermal loss is prevented by filling mineral wool (insulation) in space between the outer body & inner chamber. उन्हे के दौरान poor insulation पाया गया। 2. Door gasket fixed on the double walled door for proper sealing. उन्हे के दौरान poor sealing पायी गई। इस प्रकार Non-Responsive है।
		Laminar Air Flow (Small machine Type)	Non-Responsive	Front and side door : Polycarbonate transparent sheet thick 6 mm. उन्हे के दौरान Side Door stainless steel पायी गई। इस प्रकार Non-Responsive है।

6.	M/s Zetatek Industries Ltd., Plot no. D-31, Technocrats Industrial Estate, Balanagar (V & M) Ranga Reddy, Hyderabad-500037, Telangana Email:- info@zetatekindia.com , sales@zetatekindia.com	Hot Air Oven	Non-Responsive	निविदा में ISO 13485 & CE Certificate upload नहीं किया गया तथा RISL की फीस जमा नहीं कराई गई है तथा दस्तावेजी रूप से नॉन-रेसपोन्सिव किया गया है। इस प्रकार Non-Responsive है।
7.	M/s Authentic Instruments, 31. RIICI Indl. Area, Jhotwara, kamani Choraha, Jaipur 302012 Email:- support@authenticinstruments.com , calibration@authenticinstruments.com	Laminar Air Flow (Small machine Type)	Non-Responsive	• Front and side door ; Polycarbonate transparent sheet thick 6 mm. डेमों के दौरान Side Door glass पाया गया। इस प्रकार Non-Responsive है।

Online financial bids of responsive bidders for above item will be opened on dated 06.03.2018 at 11.00 A.M.
Demonstration report can be obtained from office during office time.


 Executive Director (EPM)
 Rajasthan Medical Services Corporation Ltd.
 Jaipur