

Rajasthan Medical Services Corporation Limited, Jaipur

Gandhi Block, Swasthya Bhawan, Tilak Marg, C-Scheme, Jaipur - 302005

Ph. No. 0141-2223887, Fax : 0141-2228065
CIN:U24232RJ2011SGC035067

E-mail : edepmrmssc-rj@nic.in
Website: http://rmsc.health.rajasthan.gov.in

No. F-8() RMSC/EPM/M-1/17-18/NIB-283/2018/ 1003

Dated: 7/3/18

OFFICE ORDER

List of bidders declared responsive/non responsive as per documentary evaluation & technical evaluation of NIB No. F-8() RMSC/EPM/M-1/17-18/NIB-283/5793 dated 12.12.17, technical bid opening date 22.01.18. The list of bidders declared responsive/ non responsive as per decision taken in the purchase committee dated 07.03.2018 headed by M.D., RMSCL:-

S. No.	Name of Firm	Quoted items	Responsive /Non responsive	Remarks
1.	M/s Sudarshan Chemicals Sudarshan building, Jhalawar road, Kota	Water Bath	Non-Responsive	तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically not approved किया गया। As per our specifications thermostatic temperature control from ambient upto 100° C. but the Temperature not reached 100° C) As per our specifications point preventing thermal runaway, seamless resevoir with no welds to leak or rust .but No seamless resevoir.
2.	M/s York Scientific Industries Pvt Ltd 8/6E, Site IV, Sahibabad Industrial Area Ghaziabad	Water Bath	Non-Responsive	तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically not approved किया गया। As per our specifications thermostatic temperature control from ambient upto 100° C. but the Temperature not reached 100° C) As per our specifications point preventing thermal runaway, seamless resevoir with no welds to leak or rust .but No seamless resevoir.
3.	M/s Chino Scientific Instruments Mfg, 3/15, panchsheel Nagar, Ajmer	Water Bath	Non-Responsive	तकनीकी परीक्षण के दौरान फर्म द्वारा सेम्पल प्रस्तुत नहीं किया गया।
4.	Prasad Overseas P.No. 4, Bhawani nikan vistar nagal road, jhotwara, jaipur	Water Bath	Non-Responsive	तकनीकी मूल्यांकन किये जाने पर फर्म की निविदा आईटम के लिये दस्तावेजी रूप से अयोग्य पाई गई। Mandatory manufacturing license and EM-II certificate is not submitted along with technical bid
5.	Prasad Overseas P.No. 4, Bhawani nikan vistar nagal road, jhotwara, jaipur	Incubator	Non-Responsive	तकनीकी मूल्यांकन किये जाने पर फर्म की निविदा आईटम के लिये दस्तावेजी रूप से अयोग्य पाई गई।

				Mandatory manufacturing license and EM-II certificate is not submitted along with technical bid
6.	M/s Sudarshan Chemical Sudarshan building, jhalawar road, Kota	Incubator	Non-Responsive	<p>तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically not approved किया गया।</p> <ol style="list-style-type: none"> 1. Showing dents in finishing of door & internal chamber 2. Loud noisy compressor during cut off/on 3. Continuously disturbing vibrating sounds 4. Spelling error (Incubator) on label 5. Burning wire smell on door opening 6. Previous unsatisfactory performance in deptt of microbiology SMS medical college.
7.	M/s York Scientific Industries Pvt Ltd 8/6E, Site IV, Sahibabad Industrial Area Ghaziabad	Incubator	Responsive	<p>तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically recommended किया गया।</p>
8.	M/s Chino Scientific Instruments Mfg, 3/15, panchsheel Nagar, Ajmer	Incubator	Non-Responsive	<p>तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically not approved किया गया।</p> <p>As per specifications suitable built in voltage stablizer. But it is not available</p> <p>Size of inner chamber – capacity approx. 10 cubic ft. but in this instrument inner chamber size 3.47 cubic ft.</p>
9.	M/s Remi Elektrotechnik Limited, Remi House, 11 CAMA Indl. Estate, Goregaun, Mumbai	Incubator	Responsive	<p>तकनीकी परीक्षण के दौरान फर्म द्वारा प्रस्तुत सेम्पल को तकनीकी समिति द्वारा Technically recommended किया गया।</p>

Online financial bids of responsive bidders for above item will be opened on dated 08.03.18 at 03:00 P.M. Demonstration report can be obtained from office during office time.


 Executive Director (EPM)
 RMSCL, Jaipur