



Rajasthan Medical Services Corporation Limited

Gandhi Block, Swasthya Bhawan, Tilak Marg, C-Scheme, Jaipur-302005 (Raj.)

Phone No: 0141-2228066 , 2228064

Website: <http://rmsc.health.rajasthan.gov.in>

CIN:U24232RJ2011SGC035067

E mail : edprmsc@nic.in

Ref. No.: F.02(96)/RMSCL/Proc/N-95 mask /NIB-07/2021/ 646 Dated: 21/11/2021

FINAL LIST OF BIDDERS DECLARED RESPONSIVE /NON RESPONSIVE

NIT Ref. No.: F.02(96)/RMSCL/Proc/N-95 mask /NIB-07/2021/291

Dated: 31.05.2021

(TECHNICAL BID OPENED ON 09.07.2021)

S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importe r	Responsive Item Code No	Non Responsive Item Code No.
1	2	3	4	5	6
1.	Emerge Glass India Pvt. Ltd Khasra No. 420/1 RIICO Industrial Area, Keshwana Rajpur Kotputli Jaipur	N-95 Mask	MSME	N-95 Mask	Nil
2.	Manohar Filaments P. Ltd 307, Phase V EHTP Industrial Estate Kundly Sonapat	N-95 Mask	Mfg	N-95 Mask	Nil
3.	Mother enterprise Shop no. 1, Jaroli Complex main Bazar Palsana Surat.	N-95 Mask	Mfg	Nil	Firm non responsive since:- 1. Profit and Loss account and Balance sheet submitted for last three financial years 2016-17, 2017-18, 2018-19 are not certified by CA. 2. Test report for standard or specification with NABL accredited laboratory not submitted.
4.	Prince Enterprise Plot no. 540, Opp. Manpasand Weight bridge Ahmedabad Santes road, Rakanpur Kalol.	N-95 Mask	Mfg	Nil	Firm non responsive since:- 1. Firm submitted average annual turnover of his sister concern Sky Life Cares ltd. 2. Firm submitted Profit and Loss account and Balance sheet of his sister concern Sky Life Cares ltd.
5.	Super plastic coats pvt ItDKh. No. 1238 Opp. Shri ram Dharm Kanta PVC Road Village Tikari Kalan Delhi.	N-95 Mask	Mfg	Nil	Firm non responsive since:-1. Undertaking regarding in-house testing facility Annexure XIV not submitted.
6.	SHOPINTERIO LIMITED LIABILITY PARTNERSHIP 9/15, First Floor, Block-9 Kalkaji extension near police station, New Delhi.	N-95 Mask	Mfg	Nil	Firm non responsive since:- 1. Firm submitted statement of Income and expenditure instead of Profit and Loss account and also firm submitted assets and Liability statement instead of Balance sheet.
7.	SURE SAFETY (INDIA) LIMITED Plot no. 220, RD-2 Panali Vadodara	N-95 Mask	Mfg	N-95 Mask	Nil
8.	ANONDITA HEALTHCARE PRODUCTS PVT LTDD-001 Sec 80	N-95 Mask	Mfg	Nil	Non responsive since:-1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration



S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importer	Responsive Item Code No	Non Responsive Item Code No.
	Noida (U.P) 201305				efficiency)2. Annual Turnover statement submitted of Group of Companies instead of participated company.3. As per balance sheet and Profit and Loss account of financial year 2017-18, 2018-19 and 2019-20 turnover is 0.81 crore while required average annual turnover is 3 crore.
9.	AOSTAF INDUSTRIES LTD Plot no. 47/7 Village Dhaturi Sonapat Haryana 131039	N-95 Mask	Mfg	Nil	Non responsive due to:- N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency and Breathing Resistance) 1. Balance Sheet and Profit and Loss account submitted by firm is not certified by C.A. 2. Bid securing declaration submitted by firm is not on stamp purchased from Rajasthan. 3. Undertaking regarding in-House testing facility are not submitted. 4. Test report for standard or specification with NABL accredited laboratory not submitted. 5. Undertaking that the items quoted by firm comply all the specifications and standards as mentioned in the tender documents not submitted.
10.	Arihant Packwell Village Kishanpura, Baddi Nalagarh Solan (HP)	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
11.	Associates Nonwovens Suketi Maza ogli, Dist. Sirmour, Kala-amb (HP)	N-95 Mask	Mfg	Nil	Non responsive due to :- 1.N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency and Splash Resistance) 2.Bid security, Tenders fees, RISL fees DD physically not submitted on time.
12.	BMA PRINTS PVT LTD 157 Sec 56 Near Devi NDRA Vihar Gurgauki 122011(HR)	N-95 Mask	Mfg	Nil	Non responsive due to:- N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 1. Average Annual Turnover and Profit and Loss account figure does not match. 2. Test report for standard or specification with NABL accredited laboratory not submitted. 3. Undertaking that the items quoted by firm comply all the specifications and standards as mentioned in the tender documents not submitted. 4. BIS certificate not submitted.
13.	CHINAR FORGE LIMITED C-85/86, Focal Point	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration



S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importer	Responsive Item Code No	Non Responsive Item Code No.
	Extension Jalandhar City Punjab				efficiency)
14.	CHOICE CHEMTECH P LTDB-30, Sec 63 Noida UP	N-95 Mask	Mfg	Nil	Non responsive since:-1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency).2.In Annexure VII monthly supply commitment mentioned not as per tender condition.
15.	Control Print Ltd Bhaton, Nr. TVS factory Bharatgas Road, Nalagarh HP 174101	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
16.	D.K. POWER ENGINEERS PVT LTD 524, HSIIDC, Barhi Industrial Area, Sonapat Haryana	N-95 Mask	Mfg	Nil	Non responsive due to:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. Bid security declaration, Tenders fees, RISL fees physically not submitted.
17.	Fashion Zone, Plot no. 136, UK Extension III, Greater Noida (UP)	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
18.	HARDIK MEDI TECH Plot no. 92, 1st Floor, Sector 57, Phase IV, Kundali Sonapat Haryana	N-95 Mask	Mfg	Nil	Non responsive since:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. Average Annual Turnover and Profit and Loss account figure does not match.
19.	HQ LAMPS MANUFACTURING CO PVT LTD	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
20.	INDUSTRIAL APPLIANCES & TECHNOLOGIES 83-84 Madhudrima House, Chanditala Dhamakhali PO GO Borara Hougly West Bengal.	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
21.	Jajot Enterprises Shri Laxmi Market Soni ji ki Nasiya Ajmer	N-95 Mask		Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
22.	kamtronics technology pvt ltd A-6, Plot No. 14/15 DLF Industrial Area Motinagar Delhi.	N-95 Mask	Mfg	Nil	Non responsive since:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. In Average annual turnover f.y. 2020-21 is unaudited.
23.	KINGFA SCIENCE & TECHNOLOGY	N-95 Mask	Mfg	Nil	Non responsive due to:- N-95 mask samples testing in laboratory does not meet the



S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importer	Responsive Item Code No	Non Responsive Item Code No.
	INDIA LIMITED Plot no. F5-5, Chakan Industrial Area, Phase - 2, MIDC Vill-Vasuli Pune				requirement as (Particulate filtration efficiency) 1. Profit and Loss account and Balance sheet for last three financial years not submitted .2. In Annexure VII estimated bid quantity and supply commitment quantity is 25.00 Lac pcs instead of 75 lac pcs.3. Manufacturing Licence not submitted from state industrial department as per bid condition clause 5 (b).4. Undertaking that the items quoted by firm comply all the specifications and standards as metioned in the tender documents not submitted.
24.	Lars Medicare Pvt. Ltd Killa 16,17 Sultanpur, Opp Sport authority of Indra Near Bahalgarh Chauk Haryana	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
25.	LAXMI SYNTHETICS 37-G, Narayan Industrial estate Anjana Farm Surat.	N-95 Mask	Mfg	Nil	Non responsive since:- 1.N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. Average annual turnover submitted by firm is less than required turnover i.e. 3 crore.
26.	MEDI WAVES INC Plot no. 92, Ground Floor, Phase IV Sector 57 Kundli Sonapat.	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
27.	MEDIMAX SAFETY & LIFESCIENCES PRODUCTS LLP IV th floor Medimaa house, Ellis. Bridge Ahmedabad	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
28.	MEGHA INTERNATIONAL 242, Industry area A near Cheema Chowk Ludhiana	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
29.	Mimaxx Electronics pvt ltd D-242, Sector 5 Bawana Industrial Area Delhi	N-95 Mask	Mfg	Nil	Non responsive since:- 1.N-95 mask samples testing in laboratory. does not meet the requirement as (Particulate filtration efficiency) 2.Joint venture a/c submitted which is not accepted.
30.	NANDANI CREATION LIMITED G-95A, RIICO Industrial Area, Phase II, Bagaru Rajasthan	N-95 Mask	MSME	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
31.	P.A.R.K. NON WOVEN PVT LTD Plot no. 298 Sec. 2 Part-I Huda, Panipat 132103 Haryana	N-95 Mask		Nil	Non responsive since:- 1.N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)



S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importe r	Responsive Item Code No	Non Responsive Item Code No.
32.	Paramount Surgimed LtdA-106, RIICO Industrial Area, Bhiwadi 301019	N-95 Mask	MSME	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
33.	Piramal Nextgen Industries Private Limited 401-404, Neelam Centre, B-Wing Hind Cycle Road, Worli, Mumbai	N-95 Mask	Mfg	Nil	Non responsive since:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. Profit and Loss account and Balance sheet of financial year 2020-21 submitted which is not considered in tender.
34.	PROMAX SAFETY AND FIRE SERVICES Plot no. 111, New GIDC Gundlav, Valsad.	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
35.	RAMDEV BEAUTY COLLECTION GR Plot no. 46, Rup Sagar, Soc Gaushala AK Road, Surat.	N-95 Mask	Mfg	Nil	Non responsive due to:- N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 1. Profit and Loss and Balance Sheet for last three years is not certified by CA. 2. Undertaking that the items quoted by firm comply all the specifications and standards as metioned in the tender documents not submitted.
36.	RAMON SURGICAL CO. B-68 GT Karnal Road, Industrial Area Delhi.	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency and Splash Resistance)
37.	Rexon Laboratories LimitedD-5 Sports and Surgicals complex kapurthala Jabalpur Punjab.	N-95 Mask	Mfg	Nil	Non responsive due to:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. In Annexure VII monthly supply commitment is 7 lac pcs while required 10 lac pcs. 3. Undertaking that the items quoted by firm comply all the specifications and standards as metioned in the tender documents not submitted.
38.	Sanmati Packaging 216/1 Khurbura Mohalla Bindal Road Dehradun	N-95 Mask	Mfg	Nil	Non responsive due to:- 1. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency) 2. Bid security declaration stamp purchased from where is not clear stamp has no signification of Rajasthan.
39.	SHREE SHYAM SALES 3852, 11nd Floor, Gali Lohe wali, Chawan	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)



S. No	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importer	Responsive Item Code No	Non Responsive Item Code No.
	Bazar, Delhi -6				
40.	Suchi Industries Limited Block-111, Sso.No. 1 Vill. Bagumara Kadodra-Bardali Road Palsana	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
41.	Sanson Promo Innovations LLP Plot no. 23, Sector 57, Phase IV HSIIDC Industrial State Kundli Sonipat Haryana	N-95 Mask		Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
42.	TIJARJA POLYPIPES LTD SP-1-2316, RICO Industrial Area, Ramchandrapura, Sitapura Jaipur	N-95 Mask		Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
43.	True Drug Pharma Pvt. Ltd Plot no. B/18-3 Susml Vanz Sachin, Tah. Chorasi Dist. Surat.	N-95 Mask		Nil	Firm non responsive due to :- 1. Bid security, Tenders fees, RISL fees DD physically not submitted. 2. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
44.	UNITY HEALTHCARE C-24, Preet Vihar, Delhi 110092	N-95 Mask	Proprietor	Nil	Firm non responsive due to:- 1. Certificate of incorporation of company not submitted. 2. Profit and Loss account and Balance sheet submitted with name Rekha Gupta (Proprietor) 3. Undertaking that the items quoted by firm comply all the specifications and standards as mentioned in the tender documents not submitted. 4. N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
45.	Vastra Fashions Plot no. 90, Sector 04, IMT Manesar, Gurugram Haryana	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)
46.	Venus Safety & Health Pvt Ltd L-75/76 Taloja MIDC Tandre Village Raigad	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)



S. No.	Name of Bidder	Quoted Item No.	Bidder Status Mfg/Importer	Responsive Item Code No	Non Responsive Item Code No.
47.	VIJAY SABRE SAFETY PVT LTD Plot no. 11 Survey no. 46/IP Daman Ganga Industrial Estate Athal Sitrasa, Dadra and Nagar Haveli.	N-95 Mask	Mfg	Nil	Non responsive due to N-95 mask samples testing in laboratory does not meet the requirement as (Particulate filtration efficiency)

NOTE: - ONLINE FINANCIAL BID WILL OPEN ON 02.11.2021 at 03.00 PM.

(Handwritten Signature)
2/11

Executive Director (Proc.)
RMSCL

